



REPÚBLICA DE PANAMÁ
AUTORIDAD AERONÁUTICA CIVIL
DEPARTAMENTO INFORMACIÓN AERONÁUTICA
Sección de Publicaciones Aeronáuticas

Direcciones:
AFS: MPLBOYX
Comercial: AEROCIVIL Panamá
Tel.: (507) 520-1595 / 1596 / 1594 ó
Fax: (507) NIL
e.mail: aispanama@aeronautica.gob.pa

Apartados 0816-03073 ó
0816-03187
Zona 5, Panamá
Apartado 0843-02086
Balboa, Ancón

SUP

A22/24

1°- Noviembre- 2024

AD

A-22/24 **Cap. SCARLETT R. MARTÍNEZ L. INTL AP. (MPSM)**
ILS fuera de servicio

Hasta el **30 DE JUNIO DE 2025**,
ILS/GS/DME identificación ASM en
frecuencia 335.0MHz/CH40X estará
fuera de servicio.

Localizador ILS/LOC identificación
ASM en frecuencia 110.3MHz estará
fuera de servicio.

REF AIP AD 2.8-16 (30 SEP 2019)

REF AIP AD 2.8-33 (30 SEP 2021)

ESTE SUPLEMENTO REEMPLAZA AL SUPLEMENTO A33/23



REPUBLIC OF PANAMÁ
CIVIL AVIATION AUTHORITY
AERONAUTICAL INFORMATION DEPARTMENT
Aeronautical Publications Section

Address: MPLBYOYX
AFS: MPLBYOYX
Commercial: AEROCIVIL Panamá
Tel.: (507) 520-1595 / 1596 / 1594 ó
Fax: (507) NIL
e.mail: aispanama@aeronautica.gob.pa

P.O. Box 0816-03073 ó
0816-03187
Zone 5, Panamá

P.O. Box 0843-02086
Balboa, Ancón

SUP

A22/24

November 1st, 2024

AD

A-22/24 CAP. SCARLETT R. MARTÍNEZ L. AP INTL (MPSM).
ILS out services

Until **JUNE 30, 2025**, the ILS/GS/DME
ASM on frequency 335.0MHz/40X will
out of service.

The Localizer ILS/LOC ASM on frequency
110.300MHz will out of service.

REF AIP AD 2.8-16 (30 SEP 2019)
REF AIP AD 2.8-33 (30 SEP 2021)

THIS SUPPLEMENT REPLACES SUPPLEMENT A33/23