



REPÚBLICA DE PANAMÁ
AUTORIDAD AERONÁUTICA CIVIL
DEPARTAMENTO INFORMACIÓN AERONÁUTICA
Sección de Publicaciones Aeronáuticas

Direcciones:
AFS: MPLBYOYX
Comercial: AEROCIVIL Panamá
Tel.: (507) 520-1595 / 1596 / 1594 ó
Fax: (507) NIL
e.mail: aispanama@aeronautica.gob.pa

Apartados 0816-03073 ó
0816-03187
Zona 5, Panamá
Apartado 0843-02086
Balboa, Ancón

SUP

A04/25

1° - Enero - 2025

AD

A-04/25 PANAMÁ PACÍFICO AP INTL (MPPA)

Luces fuera de servicio.

Hasta el **31 DE MAYO DE 2025**,
las luces de la calle de rodaje E y F
estarán fuera de servicio.

Las aeronaves deberán utilizar el
procedimiento FOLLOW ME.

ESTE SUPLEMENTO CANCELA EL NOTAM A1234/24



REPUBLIC OF PANAMÁ
CIVIL AVIATION AUTHORITY
AERONAUTICAL INFORMATION DEPARTMENT
Aeronautical Publications Section

Address:
AFS: MPLBYOYX
Commercial: AEROCIVIL Panamá
Tel.: (507) 520-1595 / 1596 / 1594 ó
Fax: (507) NIL
e.mail: aispanama@aeronautica.gob.pa

P.O. Box 0816-03073 ó
0816-03187
Zone 5, Panamá
P.O. Box 0843-02086
Balboa, Ancón

SUP

A 04/25

January 1st, 2025

AD

A-04/25 PANAMÁ PACÍFICO INTL AP (MPPA)
Lights out of service.

Until **MAY 31, 2025**, the taxiway
lights E and F will be out of service.
Aircraft must use the FOLLOW ME
procedure.

THIS SUPPLEMENT CANCELS THE NOTAM A1234/24